



PREDATOR ORION 3000





figure will vary depending on system memory, installed

Bundled software may vary depending on hardware

drivers, BIOS settings and other factors.

configuration, OS and regional availability.

Product views		5. Microphone jack	Two USB 3.2 Gen 1 (5 Gbps)
		5. Two USB 2.0 (480 Mbps)	Type-A ports
	Type-A port	Type-A ports	10. Audio jacks
		7. Ethernet (RJ-45) port	Power connector
		3. Two USB 2.0 (480 Mbps)	
	4. Headset/speaker jack	Type-A ports	
Operating system ^{1, 2}	Windows 11 Home 64-bit.		
CPU and chipset ¹	Intel® Core™ i7 14th gen processors, Intel® UHD Graphics 770		
	Chipset: Intel® B760 Chipset		
Memory ^{1, 3, 4}	16 GB DDR5 5600 MHz UDIMM		
	● Up to 64 GB of Dual-channel DDR5 4000 MHz		
Storage ^{1, 5}	Hard disk drive		
	1024 GB GB M.2 2280 PCIe Gen 4 SSD		
Graphics ⁶	NVIDIA® GeForce® RTX™ 4060 with 8	GB of GDDR6X	
Audio	DTS:X® Ultra		
Communication	WLAN:		
	● 802.11ax/ac/a/b/g/n, Wi-Fi 6E and B	luetooth® 5	
Expansion slot(s)	• PCIe x16 slot(s): 1		
	PCIe xl slot(s): 1		
	M.2 slot (for SSD): 2		
	M.2 slot (for WLAN): 1		
Windows Desktop	In-House	Search	
Apps ⁷	 Acer Care Center 	PredatorSens	se
	 Acer Configuration Manager 		
	 Acer Product Registration 		
	 Acer User Experience Program Frame 	work Warranty :	
	 Power Management Setting 	3 years carry ir	n
	Quick Access		
	 Storage Utilities 		
Dimensions	175 (W) x 377 (D) x 385 (H) mm (6.89 x	14.84 x 15.16 inches)	
Power supply and	Power supply	,	
adapter	• 500 W PFC, auto-sensing, 80PLUS#	Gold, ATX	
System compliance	RoHS, ENERGY STAR®	- , · · ·	
Certification	BSMI, VCCI, CE, FCC, CB,		
	ary depending on model.	6. Total available graphi	cs memory comprises dedicated video
	e is required to enjoy the advantages of 64		nory, and shared system memory. This
bit processing	, , , ,		iding on sustan mamoru installad

In a continuing effort to improve the quality of our products, information in this document is subject to change without notice. Images shown are only representations of some of the configurations available for this model. Availability may vary depending on region. As a phenomenon known to thin-film transistors (TFTs), liquid crystal displays (LCDs) commonly exhibit a small number of discoloration dots, as so-called "non-conforming pixels." This phenomenon is a limitation of TFT LCD technology, not a product defect, and as such is not covered by Acer's warranty. © 2023 All rights reserved.

Microsoft and Windows are registered trademarks of Microsoft Corporation.

Ultrabook, Celeron, Celeron Inside, Core Inside, Intel Logo, Intel Arc graphics, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside Logo, Intel VPro, Intel Evo, Pentium, Pentium Inside, VPro Inside, Xeon, Xeon Inside, Intel Agilex, Arria, Cyclone, Movidius, eASIC, Ethernet, Iris, Killer, MAX, Select Solutions, Si Photonics, Stratix, Tofino, and Intel Optane are

performance of 4 GB or higher memory.

A 64-bit operating system is required to enjoy the ultimate

Memory speed may vary, depending on the CPU, chipset or

 $1\ \mbox{GB}$ is $1\ \mbox{billion}$ bytes. Actual formatted capacity is less and may vary depending on preloaded materials and operating environment. Recovery Management uses a portion of the stated hard disk capacity as dedicated backup space.

trademarks of Intel Corporation or its subsidiaries.

About Acer

3.

4.

5.

bit processing.

memory fitted.

Founded in 1976, Acer is one of the world's top ICT companies with a presence in more than 160 countries. As Acer evolves with the industry and changing lifestyles, it is focused on enabling a world where hardware, software and services will fuse with one another, creating ecosystems and opening up new possibilities for consumers and businesses alike. Acer's 7,500 employees are dedicated to the research, design, marketing, sale, and support of products and solutions that break barriers between people and technology. Please visit www.acer.com for more information.